

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : WESTBANK ASBESTOS
LOCATION : Jefferson Parish, LA
SITE NUMBER: LAD985170711
SURVEY DATE: 2/8/90 INSPECTED BY: STATE FIT TAT OTHER: _____
LABORATORY : CLP EPA OTHER _____

RECEIVED FROM: JOHN JONES DATE RECEIVED: 11/12/92

SAMPLE TYPE(s):

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

<u>N</u> (Re)Sampling Requested	<u>N</u> Locate Drinking Water Sources
<u>N</u> Further Action is URGENT	<u>-</u> Keep Site Active ("N"=No Further Action)
	<u>-</u> Concur with Report Recommendations

SUMMARY:

From 1955-1965 this facility produced asbestos containing products. Asbestos Containing Waste Materials (ACWM) were processed and given away to local residents for use in driveways and rights of way. The friable material is readily visible in many local driveways.

Considering the immobility of asbestos in groundwater and the impermeability of the soil in the area, the groundwater pathway is very unlikely. There are no drinking water intakes within 15 miles downstream of the site on the surface water pathway.

The threat to drinking water is minimal at this site.

Concurrence:

F. Warren Morris 12/30/92

Neil K. Krum
ENGINEER/REVIEWER

12/30/92

919505

